

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Spring	Spring	11/29/2010		.078	177.5
	Well	Outside Faucet	03/19/2009		.49	160.9
			12/15/2009	.069	84.8	
	Well	Kitchen Sink	02/20/2009		.79	204.7
		KITCHEN FAUCET	07/13/2010		2.5	131.8
			12/15/2009	< .01	185000	
			01/21/2009		< 7.92	
			07/17/2008			
			10/06/2010	< .01		
	Well	Kitchen Sink	07/12/2010	< .025	24000	-61.4
	Well	Well Head	09/18/2010			
	Well	Outside Spigot Front Porch	10/12/2011		1300	142.5
	Well	Kitchen Sink	07/12/2010	.279	25000	3.9
	Well	Kitchen Sink	10/07/2010		31000	-105.3
	Well	Wellhead	09/18/2010			
	Well	Kitchen Sink	02/17/2009		.72	103.2
	Well	Kitchen Sink	01/25/2009		5.6	
	Well	KITCHEN SINK	01/13/2011		28	168
			08/13/2008			
	Well	Kitchen Sink	01/25/2009		.26	
	Well	KITCHEN SINK	02/28/2010		< .1	128.1
	Well	Well	06/16/2008			
	Well	Bathroom Sink	07/30/2010		16000	-120.8
	Well	Barn Spigot	10/21/2011		37000	92.1
	Well	Kitchen Sink	08/06/2009		290	31
	Well	BATHROOM FAUCET	04/25/2010		510	134.5
	Well	* BATHROOM SINK	12/14/2009		600	-15.9
	Well	KITCHEN SINK	12/08/2010		.32	216.9
	Well	BASEMENT AT PRESSURE	02/08/2010		.52	118.9
			10/21/2010	< .01	0	
			10/27/2010	< .01	0	
	Well	At Pressure Tank in Water Tr	08/03/2011		.14	155
	Well	At Pressure Tank in Water Tr	08/17/2011		.19	207.5
	Well	UPSTAIRS KITCHEN SINK	02/03/2011		.32	151.1
	Drilled Well	Upstairs Kitchen Sink	03/03/2011		.44	208.1
	Well	Kitchen Sink Faucet	01/20/2011		.55	168.7
	Well	After Treatment System in Sy	10/18/2011		.63	212
	Well	At Pressure Tank in Water Tr	09/28/2011		.67	262.5
	Well	Kitchen Sink Faucet	07/06/2011		.84	200.5
	Well	KITCHEN FAUCET	01/07/2011		1.2	175.4
	Well	Kitchen Sink Faucet	05/24/2011		1.2	150.3
	Well	At Pressure Tank in Water Tr	09/15/2011		1.2	230.8
	Drilled Well	Upstairs Kitchen Faucet	02/17/2011		1.4	206.1
	Well	Kitchen Sink Faucet	05/10/2011		1.4	115.9
	Well	Kitchen Sink Faucet	06/07/2011		1.4	186.6
	Well	Upstairs Kitchen Sink	07/20/2011		1.4	255
	Well	Before Treatment System in S	10/11/2011		1.5	259
	Well	KITCHEN FAUCET RENTAL	12/21/2010		1.7	152.7
	Well	Before Treatment System in S	10/25/2011		1.7	145.1
	Well	Kitchen Sink Faucet	06/21/2011		1.8	124.5
	Well	Other (list)	12/20/2011		2.2	158.4
	Drilled Well	Upstairs Kitchen Sink	03/17/2011		2.3	149.7
	Drilled Well	Upstairs Kitchen Sink	03/31/2011		2.6	176.5
	Well	KITCHEN FAUCET	04/12/2011		2.8	210.3
	Well	Before Treatment in Shed	01/05/2012		2.8	177.5
	Well	UPSTAIRS KITCHEN SINK	04/26/2011		2.9	185.3
	Well	before treatment system in sy	11/08/2011		4.1	375.9
	Well	Before Treatment System in S	10/18/2011		8.3	187.9
	Well	Other (list)	12/08/2011		10	155.2
			01/27/2009		13.8	
	Well	At Pressure Tank in Water Tr	08/31/2011		14	162.9
	Well	Kitchen Sink	02/12/2009		21	
	Well	Other (list)	11/21/2011		29	250
	Well	Kitchen Sink	02/11/2011		< .1	156
			01/12/2009		< 7.92	
	Well	Kitchen Sink	07/01/2010		.24	169.2
	Well	Kitchen Sink	07/28/2009		.49	47
	Well	Kitchen Sink	03/12/2009		.52	129
	Well	Kitchen Sink	08/20/2009		20	164.4
	Well	Kitchen Sink	11/09/2008			
			10/14/2009			79.5
	Well	Kitchen Sink	06/22/2011			161.8
	Tank	Kitchen Sink- Provided Water	11/29/2010		.22	163.3
	Tank	Kitchen Sink- Provided Water	09/08/2010		.46	152.9
	Tank	Kitchen Sink- Provided Water	10/26/2010		.5	156.1
	Tank	Kitchen Sink- Provided Water	07/27/2010		.55	160

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Tank	Kitchen Sink- Provided Water	08/25/2010		.57	160.2
	Tank	Kitchen Sink- Provided Water	05/16/2010		1.4	129.3
	Tank	Kitchen Sink- Provided Water	06/04/2010		1.6	106.1
	Tank	Kitchen Sink- Provided Water	04/25/2010		2.2	162.3
	Tank	Kitchen Sink- Provided Water	03/04/2010		2.9	187
	Tank	Kitchen Sink- Provided Water	02/02/2010		15	177.6
	Tank	Kitchen Sink- Provided Water	01/04/2010		45	196.9
			11/18/2010	.023	1720	
	Well	Well	07/20/2011		3350	
	Well	Lawn Hydrant	10/11/2011		3700	
	Well	Lawn Hydrant	08/11/2011		3770	
	Well	Lawn Hydrant	09/15/2011		5350	
	Well	Under Trailer	08/13/2009		8100	41.7
	Well	Under Trailer	11/23/2009		8400	106.8
			12/07/2010	.088	8900	
	Well	Outside Faucet under Trailer	07/20/2009		9000	148.8
	Well	Under Trailer	10/30/2009		9000	70.1
	Well	Before Treatment - Under Tra	02/20/2009		9100	177.1
	Well	Outside Faucet	05/13/2009		9100	405.7
	Well	Before Treatment - Outside F	06/14/2009		9100	53.3
			01/27/2009		10200	
			05/14/2009	.021	11100	
	Well	Under Trailer	09/15/2009		12000	105.8
	Well	Before Treatment - Under Tra	10/12/2009		13000	400.9
	Well	Under Trailer	12/10/2009		13000	67.8
			06/30/2009	.032	13900	
	Well	Outside Faucet	04/14/2009		14000	99.2
			10/19/2010		15100	
			11/02/2010	.057	15300	
			10/12/2010	.287	15600	
			05/14/2009	.032	16400	
			11/22/2010		16700	
	Well	At Well Head from Spigot	12/15/2011		16800	
			11/15/2010	.055	17200	
			11/08/2010	.062	17700	
			01/13/2009		17900	
			02/04/2009		18800	
			09/23/2010	.413	18800	
			06/30/2009	.015	20000	
			10/26/2009	.069	20300	
			09/16/2010	.384	20800	
	Well	Kitchen Sink Faucet	10/30/2009		21000	56.5
	Well	Kitchen Sink Faucet	11/23/2009		21000	91.4
	Well	Kitchen Sink Faucet - After Tr	10/22/2009		22000	72.4
			01/27/2009		22300	
			03/26/2009	.016	22600	
	Well	Kitchen Sink Faucet	12/10/2009		25000	63.3
	Well	Lawn Hydrant	10/25/2011		< 5	
			07/09/2008			
			11/20/2008	< .025		
	Well	Kitchen Sink	11/20/2008			
			10/19/2010	.098		
			10/26/2010	.137		
			04/26/2011			
	Well	Kitchen Sink Faucet	11/19/2009		110	71
	Wet Meadow	Pressure Tank	11/19/2009		150	62.4
			05/12/2010	< .01	0	
			11/17/2010	< .01	0	
	well	KITCHEN SINK	02/28/2010		.39	128.7
			02/13/2009		< 7.92	
			05/28/2008			
	Well	Kitchen Sink	12/06/2009		.63	207
	Well	PRESSURE TANK IN BARN	12/06/2009		.85	198.7
			02/18/2008			
	Well	Kitchen Sink from Spring fed	11/05/2008			
			01/27/2009		385	
			05/28/2008			
	Well	KITCHEN SINK	07/11/2010	.066	22000	112.3
	Well	Kitchen Sink	07/13/2010	.058	24000	66.4
	Well	Barn Spigot	09/10/2010	.076	24000	12
			10/07/2010	.098	29300	
	Well		12/15/2009		54200	
	Well	Wellhead	09/18/2010			
	Well	PRESSURE TANK IN BASEM	05/20/2010	< .025	7100	228.5
			10/28/2010	.041	9690	
	Well	Spigot beofre pressure tank	10/12/2011		11000	265.1

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	Trailer #1 Kitchen faucet	Hot 11/19/2010		13000	10.8
	Well	Spigot in Laundry	09/10/2010	< .025	17000	146.9
	E		05/10/2011		22000	
	E		07/05/2011	.016	23100	
	E		11/03/2010	.03	24600	
	Well	TRAILER #1 KITCHEN SINK	11/19/2010		29000	-107.3
	Well	TRAILER #1 BASEMENT SP	11/19/2010		30000	12.5
	E		08/11/2010	.062	31500	
	E		10/27/2010	.016	31600	
	E		12/02/2010	.019	31600	
	E		12/02/2010	.019	31600	
	E		09/02/2010	.058	47900	
	E		09/22/2010	.062	49900	
	E		09/09/2010	.062	50400	
	E		10/04/2010	.059	51600	
	E		08/04/2010	.06	52400	
	E		12/15/2009	.059	54200	
	E		07/21/2010	.062	56800	
	E		06/16/2010	.058	63300	
	E		08/31/2010	.037		
	Well	Wellhead	09/18/2010			
	Well	KITCHEN SINK	04/01/2010	< .025	1.1	156.7
	Well	Basement at Pressure Tank	01/28/2010		.2	170.5
	Well	Kitchen Sink	02/26/2009		.44	163.6
	Well	Bathroom Sink	11/10/2010		< .1	154.3
	Well	Kitchen Sink	11/09/2008			
	BO		07/09/2010	< .025	.23	109.2
	BO		05/10/2011		.23	
	Well	PRESSURE TANK	12/15/2009		.23	196
	Well	Basement at Pressure Tank	03/16/2009		.5	166.1
	Well	Downstairs Spigot	09/21/2008			
	Well	Apartment Bathroom Sink	03/04/2010		220	-197.8
	Well	POST OFFICE - BATHROOM	03/04/2010		.2	59.3
	Well	BASEMENT AT PRESSURE	01/14/2010		.29	145
	Well	At Well Head	11/19/2009		1600	-23.5
			03/25/2008			
	Well	Well	09/27/2008			
			01/27/2009		5520	
	well	OUTSIDE HYDRANT	04/22/2010		23000	-14.7
			01/18/2009		30900	
	Well	Outside Hydrant	04/26/2009		32000	
			07/21/2010	.043	32500	
			10/26/2010	.042	33200	
			11/02/2010	.044	34500	
			03/18/2009		34700	
			11/15/2010	.042	34900	
	Well	Outside Faucet	10/27/2011		35400	
			12/07/2010	.049	36500	
			11/08/2010	.045	38600	
			10/12/2010	.018	39600	
			08/24/2010	.047	39700	
			07/08/2010		40200	
			11/22/2010	.04	40600	
			08/04/2010	.044	41100	
			05/27/2010	.047	41600	
			08/11/2010	.028	42100	
			07/29/2010	.046	42500	
			09/21/2010	.017	43000	
			05/06/2010	.051	43200	
			08/31/2010		43500	
			10/19/2010	.033	43700	
			06/24/2010	.05	45600	
			06/09/2010	.051	46100	
			09/08/2010	.01	47000	
			09/16/2010	.012	51100	
			06/15/2010	.084	54800	
			09/29/2010	.011	56900	
			12/16/2008	.026		
			08/18/2010	.047		
	Well	At Well Head from Spigot	12/14/2011		13100	
	Well	Kitchen Sink Faucet	01/06/2009		19000	
	Well	Kitchen Sink Faucet	04/14/2009		19000	-73.7
	Well	At Well Head from Spigot	10/26/2011		20500	
			01/27/2009		20900	
	Well	At Well Head from Spigot	07/20/2011		21600	
	well	OUTSIDE SPIGOT	03/11/2010		22000	-25.9

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	Not Reported	05/18/2009		23000	
	well	OUTSIDE SPIGOT	05/27/2010		23000	-101.4
	Well	Kitchen Sink Faucet	02/12/2009		24000	
	well	OUTSIDE SPIGOT	02/04/2010		24000	43.1
	Well	Kitchen Sink Faucet	09/29/2009		25000	297.2
	well	Outside Spigot on Main House	06/07/2010		25000	-78.3
	Well	OUTSIDE SPIGOT	08/26/2010		25000	-224.7
	Well	Kitchen Sink Faucet	07/23/2009		27000	1.7
	Well	Kitchen Sink Faucet	08/13/2009		28000	-269.4
	well	OUTSIDE SPIGOT	04/15/2010		28000	-116
	Well	Kitchen Sink Faucet	06/14/2009		29000	-239
	well	OUTSIDE FAUCET	12/03/2009		29000	-80.6
	Well	At Well Head from Spigot	08/11/2011		31900	
	well	OUTSIDE SPIGOT	01/07/2010		33000	36.6
	Well	OUTSIDE SPIGOT	07/29/2010		33000	-166.2
			10/13/2010	.146	37300	
			09/23/2010	.088	37400	
			09/16/2010	.059	38400	
			10/21/2010	.144	39300	
			12/08/2010	.027	40900	
			01/18/2009		42700	
			07/23/2009	.016	43600	
			07/15/2010	.035	45300	
			07/21/2010	.132	64300	
			07/09/2008			
	Tank	KITCHEN SINK PROVIDED WATER	11/29/2010		.13	206.9
	Tank	KITCHEN SINK- PROVIDED	02/15/2010		.18	317.8
	Tank	KITCHEN SINK - PROVIDED	03/04/2010		.19	239.8
	Tank	KITCHEN SINK -PROVIDED	01/07/2010		.2	265.4
	Tank	KITCHEN SINK- PROVIDED	04/24/2010		.4	251.7
	Tank	Kitchen Sink Provided Water	11/12/2009		1.1	559.1
	Tank	KITCHEN SINK -PROVIDED	12/03/2009		2.3	147
			06/30/2009	< .01	378	
	Well	Kitchen Sink After Treatment	08/13/2009		1500	
			06/30/2009	.041	1630	
	Well	Pressure Tank Before Treatment	08/13/2009		2000	
			01/27/2009		2140	
	Well	Outside Hose After Treatment	06/20/2009		2800	191
	Well	After Treatment	07/23/2009		3600	
	Well	Pressure Tank Before Treatment	09/21/2009		3700	76.7
	Well	Kitchen Sink After Treatment	05/13/2009		3800	
	Well	Kitchen Sink After Treatment	10/14/2009		4500	56.2
			04/14/2009		4970	
	Well	Outside Faucet After Treatment	04/14/2009		5500	
	Well	Kitchen Sink After Treatment	09/21/2009		10000	35
	Well	Holding Tank Before Treatment	04/14/2009		12000	
			04/14/2009		12200	
	Well	Pressure Tank	10/25/2011		15200	
	Well	Holding Tank Before Treatment	05/13/2009		16000	
	Well	Holding Tank Before Treatment	06/20/2009		18000	43.9
	Well	Pressure Tank Before Treatment	07/23/2009		19000	
			05/27/2010	.037	28100	
			07/06/2010	.084	29300	
			11/22/2010	.022	29400	
			11/15/2010	.021	29700	
	Well	Holding Tank	02/12/2009		30000	
			09/29/2010	.03	31400	
			10/19/2010	.044	32000	
	Well	At Pressure Tank in Basement	12/16/2011		32400	
			09/02/2010	.081	32500	
			07/13/2010	.086	32800	
			11/08/2010	.018	35800	
			08/18/2010	.066	38900	
	Well	Pressure Tank Before Treatment	10/14/2009		40000	71.2
			08/24/2010	.063	40100	
			10/13/2010	.03	44300	
			08/04/2010	.044	45000	
			10/26/2010	.023	45400	
			01/18/2009		47700	
			09/16/2010	.057	47900	
			12/07/2010	.032	48500	
			09/21/2010	.055	49000	
			06/09/2010	.018	49600	
			07/29/2010	.026	50200	
			06/15/2010	.019	50800	
			05/06/2010	.013	51000	

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
			08/11/2010	.04	53100	
			07/21/2010	.071	58800	
			09/09/2010	.096	61200	
			05/28/2008			
Well		Outside Spigot	07/30/2010	.076	24000	-155.3
Well		Pressure Tank	01/28/2010		35000	45
Well		Pressure Tank	12/21/2009		43000	65.3
Well		Outside Spigot	11/05/2010		43000	-138.3
Well		Kitchen Sink Main House	02/08/2010		1.8	118.6
Well		Barn Faucet	02/08/2010		5.1	86.3
			03/17/2009	< .01	0	
			11/18/2009	< .01	0	
			08/31/2010		0	
			09/21/2010	< .01	0	
			10/13/2010	< .01	0	
			10/21/2010	< .01	0	
			10/28/2010	< .01	0	
			11/09/2010	< .01	0	
Well		Kitchen Sink Faucet	05/07/2009		.61	160.6
Well		Bathroom Sink	03/16/2009		2.4	128.6
			01/13/2009		8.03	
			09/08/2010	< .01	8.06	
			11/02/2010	< .01	8.94	
			09/30/2010	< .01	9.15	
			09/16/2010	< .001	9.28	
			04/27/2010	.023	11.1	
well		BASEMENT AT PRESSURE	12/14/2009		12	93.4
			03/17/2010	< .01	18	
			07/09/2008			
			05/06/2010	< .01		
Tank		Provided Water	09/23/2010		1.2	189.6
Well		From Cold Water Hose	12/14/2011		138	
			12/02/2010	.214	170	
Well		Outside Faucet	10/11/2011		340	
Well		Outside Faucet	08/09/2011		402	
			11/23/2010	.37	457	
Well		Outside Faucet	07/20/2011		457	
			09/16/2010	.216	491	
Well		Outside Faucet	10/26/2011		738	
			10/21/2010	.084	1080	
			09/23/2010	.123	1650	
			11/03/2010	.064	2020	
Well		Bathroom tub faucet	05/13/2009		2200	
			01/05/2009		4010	
Well		Bathroom tub faucet	08/13/2009		4200	
			06/30/2009	< .01	4580	
Well		Bathroom tub faucet	02/26/2009		4900	
Well		Bathroom tub faucet	07/20/2009		5100	161.6
Well		Kitchen Sink Faucet	09/21/2009		5200	84.2
			04/30/2009		5880	
Well		Bathroom tub faucet	04/14/2009		6500	177
Well		Bathroom tub faucet	06/14/2009		6600	71.1
Well		Direct from Well	01/22/2009		8200	
well		PRESSURE TANK	10/22/2009		9700	69.4
Well		Kitchen Sink Faucet	10/22/2009		10000	84.8
			10/21/2009	.011	10300	
			02/03/2009		12300	
			03/26/2009	< .01	15500	
			09/21/2008			
			12/08/2010	.199		
Spring		Spring Overflow Pipe	03/31/2010	< .025	.83	145.9
			07/17/2010	< .025	5.5	157.8
Spring		Spring Culvert	11/18/2010		.049	182.3
Spring		Pressure Tank	07/09/2010	< .025	.12	170.9
			05/10/2011		.12	
Spring		Kitchen Sink - Debonis Prope	07/09/2010	< .025	.23	109.2
			05/10/2011		.23	
Spring		SURFACE AT SPRING HOUSE	06/24/2010		.26	191.5
Spring		Stream	07/09/2010	< .025	10	120.9
Pond		Pond	07/09/2010	< .025	51	58.3
Well		Kitchen Sink	04/19/2009		.41	125.3
			02/04/2009		< 7.92	
Well		Barn After Filter	04/08/2009		.16	194.3
Well		Pressure Tank	07/27/2010		.17	142.4
Well		Kitchen Sink	04/08/2010		.18	175.8
Well		Pressure Tank	12/15/2009		.54	127.7

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	Kitchen Sink	08/20/2010		20	166.2
	Well	Kitchen Sink	03/16/2009		< .1	170.7
			09/22/2008			
	Well	Kitchen Sink	01/31/2010			197.7
	Well	Well Head	04/04/2009		1.5	100.5
	Well	Kitchen Sink	02/17/2009		1.7	142.2
	Well	OUTSIDE SPIGOT	02/11/2011		.23	153.3
	Well	After Treatment System In Tre	09/28/2011		2.2	211.3
	Well	Outside spigot on North side	09/21/2011		20	79
			10/07/2010	< .01	20.7	
	Well	After Treatment System In Tre	10/05/2011		27	331.7
	Well	Outside spigot on North side	09/07/2011		36	200.9
	Well	After Treatment System In Tre	10/18/2011		37	190.2
	Well	After Treatment System In Tre	10/11/2011		39	259.4
	Well	After Treatment System in sys	09/15/2011		50	222.6
			01/21/2009		66.5	
	Well	After Treatment System In Sh	11/03/2011		83	56.8
			08/31/2010	.012	118	
			09/21/2010	< .01	120	
	Well	Other (list)	12/01/2011		120	197.8
	Well	After Treatment System In	11/08/2011		150	292.3
	Well	After Treatment System In	11/17/2011		160	202.2
	Well	Other (list)	11/21/2011		170	232.1
	Well	Kitchen Sink Faucet	02/20/2009		210	188.3
	Well	After Treatment System	06/23/2011		280	121.8
			09/08/2010	.01	293	
			10/13/2010	< .01	379	
			09/15/2010	< .01	440	
	Well	Outside spigot on North side	07/20/2011		480	192
			08/24/2010	.02	569	
			10/21/2010	< .01	814	
	Well	KITCHEN FAUCET	10/27/2010		1200	115.9
			08/18/2010	.026	3550	
	Well	Outside Spigot	07/07/2011		3700	129.4
	Well	Outside spigot on North side	08/03/2011		4400	167
	Well	Before Treatment	10/11/2011		4400	256.8
	Well	Before Treatment System In T	09/28/2011		5200	227
			08/11/2010	.029	6780	
	Drilled Well	Outside Spigot	03/17/2011		7000	156.9
			07/29/2010	.021	7970	
	Well	After Treatment System In Tre	10/25/2011		8400	189.1
	Well	Before Treatment System In T	10/25/2011		8400	189.1
	Well	Before Treatment System in s	09/15/2011		8600	236.1
			08/04/2010	.026	9850	
			07/21/2010	.026	11300	
	Well	Outside Spigot on Main Hous	06/07/2011		12000	135.8
	Well	SPIGOT ON KITCHEN SINK	03/03/2011		13000	127.9
	Well	OUTSIDE SPIGOT	02/17/2011		14000	191
	Well	Outside Spigot on Main Hous	05/24/2011		14000	145.9
	Well	Before Treatment System In S	11/08/2011		15000	291.3
	Well	Pressure Tank	06/21/2011		16000	53.1
	Well	Before Treatment	06/23/2011		17000	14.2
	Well	Before Treatment System in S	08/31/2011		18000	119
	Well	Before Treatment System in S	12/08/2011		18000	166.5
	Well	OUTSIDE SPIGOT	01/27/2011		19000	.9
	Well	Other (list)	12/20/2011		20000	187.8
	Well	Before Treatment	11/21/2011		21000	230.7
			07/08/2010		21200	
	Well	OUTSIDE SPIGOT	03/31/2011		23000	151
	Well	Outside Spigot on Main Hous	05/10/2011		23000	118
			07/13/2010	.029	23600	
	Well	OUTSIDE SPIGOT	04/26/2011		25000	170.4
	Well	Other (list)	01/05/2012		27000	181.9
	Well	OUTSIDE SPIGOT	04/12/2011		29000	164.7
	Well	KITCHEN SINK	01/10/2011		32000	168.8
			06/15/2010	.583	33300	
			04/19/2010	.21	39300	
			07/17/2008			
			12/17/2008			
	Well	Kitchen Sink Faucet	10/19/2010		.12	189
	Well	Pressure Tank	10/27/2009		.13	134.4
	well	Kitchen Sink - Ann's House	10/27/2009		.27	136.2
	Well	Kitchen Sink Faucet	04/19/2009		5.5	199.5
	Well	Kitchen Sink- Doug and Jo Ar	10/27/2009		< .1	168.5
			10/26/2009		.62	124.3
	well	PRESSURE TANK	10/26/2009		.65	145.5

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	Barn Pressure Tank	04/19/2009		2.7	191.2
well	KITCHEN SINK	05/13/2010		1.7	116.9
		10/26/2009		2	108.3
		10/26/2009		2.5	80.1
		10/26/2009		37	-18.9
		10/26/2009		37	-54.8
		05/13/2010		50	55.6
Spring	Basement at Pressure Tank	02/13/2010		.12	179.8
Spring	Basement at Pressure Tank	12/22/2009		.2	159.6
Spring	Hose from Spring	07/15/2010		.44	151.8
Spring	Basement at Pressure Tank	09/10/2010	< .025	.58	173.4
Spring	At Spring	04/19/2009		1.1	182.6
Spring	Kitchen Sink	11/08/2011		8.53	
Well	Kitchen Sink	03/25/2009		120	-39.8
		03/22/2011		185	-78
Well	Basement at Pressure Tank	12/14/2009		440	-43.8
		09/21/2008			
		10/26/2009		.14	114.4
well	PRESSURE TANK	10/26/2009		1.6	126.2
Well	Pressure Tank	06/17/2010		.13	145.8
Well	Kitchen Sink	01/13/2011		.16	173.6
Well	Bathroom Sink	11/30/2009		.41	61
		09/21/2009		1.1	332.1
		09/29/2009		1.1	
Well	Basement at Pressure Tank	11/30/2009		1.8	88.3
Well	Basement at Pressure Tank	03/25/2010		< .1	129.4
		02/10/2009		< 7.92	
		05/28/2008			
Well	Pressure Tank	03/31/2010			
Well	Kitchen	09/14/2008			
Well	Kitchen Sink	05/03/2009		< .1	139
Well	Inside Faucet	08/05/2011		< 26	
		02/23/2009		< 7.92	
		08/05/2011			
Well	Kitchen Sink	05/03/2009		.22	
Well	Inside Faucet	08/05/2011		< 26	
		02/23/2009		< 7.92	
		07/31/2008			
		08/05/2011			
		08/09/2011			
Well	Garage Faucet	12/10/2010		3.7	148.7
Well	Keith Murray Kitchen Sink	01/24/2010		.11	147.3
Well	Keith Murray Before Filter Un	02/26/2009		2.8	162.8
Well	Keith Murray Kitchen Sink	11/09/2008			
Well	Kitchen Sink	08/19/2010		.14	145.8
Well	Barn Well Milkhouse Sink	08/19/2010		.31	163.7
Well	Inside Faucet	10/14/2011		< 5	
Pond	Pond	10/14/2011		< 5	
Well	Inside Faucet	10/14/2011		< 5	
		05/03/2009		.16	
Well	LAUNDRY SINK	12/21/2009		5	122.6
Well	After Treatment System	06/10/2011		35	65.8
Well	After Treatment in System Sh	05/17/2011		150	149.2
Well	After Treatment System	06/07/2011		220	144.9
Well	After Treatment	05/04/2011		250	158.1
Well	After Treatment System	05/12/2011		320	95.1
Well	Before Treatment	06/02/2011		390	162.1
Well	Before Treatment at Outside	05/17/2011		620	167.2
Well	Before Treatment System	06/07/2011		690	153.9
Drilled Well	Before Treatment at Hydrant	06/24/2011		720	143.2
Well	Before Treatment System	05/12/2011		740	43.4
Well	Before Treatment	05/04/2011		830	155.2
Well	Before Treatment System in S	05/17/2011		850	175.1
Well	Before Treatment at Hydrant	06/30/2011		880	139.9
		11/18/2009	.023	885	
Well	Before Treatment at Hydrant	06/24/2011		910	146.2
		10/11/2011		950	37.3
		09/02/2010	.109	969	
Well	Before Treatment at Outside	05/12/2011		1000	103.5
Well	Outside Hydrant	03/31/2011		1300	139.4
Well	Outside Hydrant	04/26/2011		1300	121.5
Well	Outside Hydrant	04/12/2011		1400	152.3
Well	OUTSIDE HYDRANT	03/17/2011		1500	160.1
		09/16/2010	.067	1550	
Well	Outside Hydrant	01/20/2011		1600	147.2
Well	Before Treatment System	06/10/2011		1600	125.9

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
			11/23/2010	.035	1710	
			11/03/2010	.028	1790	
Well		OUTSIDE HYDRANT OFF OF	02/03/2011		1800	102.1
			09/29/2010	.075	1840	
			09/21/2010	.022	1860	
			10/13/2010	.156	1860	
Well		Outside Hydrant	12/21/2010		1900	119.3
Well		Outside Hydrant	01/07/2011		1900	127.8
Drilled Well		Spigot	02/17/2011		1900	181
			11/09/2010	.011	1950	
			12/02/2010	.025	2000	
			10/21/2010	.073	2020	
			12/08/2010	.028	2040	
			07/29/2010	.075	2080	
			10/28/2010	.042	2100	
Well		Outside Hydrant	03/03/2011		2200	170.2
Well		Kitchen Sink Faucet	04/27/2010		2600	118.2
			06/24/2009	< .01	3470	
			04/27/2010	< .01	3660	
Well		Kitchen Sink Faucet	08/13/2009		4800	53.2
			03/23/2009	< .01	5060	
Well		Kitchen Sink Faucet	11/09/2008			
Creek		Burdick Creek Upstream	05/08/2010			
Creek		Burdick Creek Downstream	05/08/2010			
			05/12/2010	.014		
Well		After Treatment System	06/02/2011			159.9
Well		Before Treatment at Hydrant	06/24/2011			158
Well		Before Treatment at Hydrant	06/24/2011			126.4
Well		Before Treatment at Hydrant	06/24/2011			142.9
Well		Before Treatment at Hydrant	06/24/2011			146.1
Drilled Well		Before Treatment at Hydrant	06/24/2011			124.2
Well		Before Treatment at Hydrant	06/24/2011			140.4
Well		Before Treatment at Well	10/18/2011			159.3
Spring		Kitchen Sink	07/20/2010	< .025	1.5	165.8
Well		Bathroom Sink	01/21/2009		11	
			01/26/2009		15.6	
Well		Pressure Tank	10/25/2011		7160	
			01/28/2010	.012	23600	
			05/28/2008			
Well		After Treatment System in Sy	09/07/2011		.19	248.1
Well		After treatment system- In sys	07/06/2011		.31	55.5
Well		After Treatment System in Sy	07/20/2011		.68	169
Well		After treatment system- In sys	06/21/2011		1.2	74.8
Well		After Treatment System in Sy	09/30/2011		1.8	147.5
Well		After Treatment System - She	06/29/2011		2	166.6
Well		After treatmen system- In sys	07/13/2011		3.5	149.6
Well		After Treatment System in Sy	07/27/2011		3.6	171
Well		After Treatment System in Sy	09/21/2011		5.7	228.3
Well		After treatment system- In sys	05/24/2011		6	104.4
Well		After Treatment System in Sy	10/05/2011		9.3	317.4
Well		After Treatment System in Sy	10/18/2011		9.3	166.6
Well		After Treatment System in Sy	08/31/2011		11	106.3
Well		After Treatment System in Sy	09/15/2011		14	146.2
			08/17/2011		23	154.7
Well		After Treatment System in Sy	08/10/2011		32	194.8
Well		After treatment system- In sys	06/07/2011		40	144.3
Well		After treatment system- In sys	04/26/2011		58	129
Well		After treatment system- In sys	06/14/2011		74	123.6
Well		After Treatment System In Sy	08/03/2011		80	118
Well		AFTER TREATMENT	12/16/2010		95	124.3
Drilled Well		After treatment system- In sys	03/10/2011		96	115.4
Drilled Well		After treatment system- In sys	02/24/2011		130	132.8
Well		AFTER TREATMENT SYSTE	01/06/2011		140	154.7
Drilled Well		After treatment system- In sys	03/24/2011		140	126.6
Well		after treatment system in syst	11/08/2011		140	222.1
Well		After treatment system- In sys	02/03/2011		160	128.6
Well		After treatment system- In sys	05/10/2011		160	84.2
Well		After Treatment System in Sy	10/25/2011		160	142.1
Well		After Treatment System in Sy	01/20/2011		170	136.7
Drilled Well		After treatment system- In sys	03/03/2011		170	146.1
Well		Other (list)	11/21/2011		180	225.5
Well		AFTER TREATMENT SYSTE	12/28/2010		190	130.3
Well		After treatment system- In sys	05/17/2011		200	162.7
Well		After Treatment System in Sy	10/11/2011		200	150.8
Drilled Well		After treatment system- In sys	01/27/2011		230	122.1
Well		after treatment system in syst	11/03/2011		230	185

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	after treatment system in sys	11/17/2011		230	162.2
	Well	Other (list)	12/01/2011		240	167.3
	Well	AFTER TREATMENT SYSTEM	04/12/2011		250	161.2
	Well	After treatment system- in sys	05/03/2011		260	191.8
	Well	After treatment system- In sys	04/19/2011		290	179.9
	Well	After treatment system- In sys	05/31/2011		310	151.3
	Drilled Well	After treatment system- In sys	03/31/2011		330	155.7
	Well	After treatment system- In sys	04/05/2011		330	120
	Well	AFTER TREATMENT SYSTEM	01/13/2011		340	162
			11/17/2010	.043	347	
	Drilled Well	After treatment system- In sys	03/17/2011		360	125.5
	Well	AFTER TREATMENT SYSTEM	12/09/2010		380	147.2
	Well	AFTER TREATMENT	12/02/2010		390	197.5
	Well	EFFLUENT FROM VALVE IN	11/20/2010		520	110.7
	Well	After Treatment System in Sy	08/24/2011		540	-7
	Drilled Well	After treatment system- In sys	02/10/2011		560	160.4
	Drilled Well	After treatment system- In sys	02/17/2011		620	174.9
	Well	EFFLEUNT FROM VALVE IN	11/23/2010		850	126.9
	Well	After Treatment System	11/05/2010		1000	-26.9
		MIDPOINT IN TREATMENT S	11/05/2010		4300	
	Well	Kitchen Sink	09/21/2009		5400	-285.2
	Well	Kitchen Sink	06/20/2009		12000	-242
	Well	PRESSURE TANK	10/25/2009		13000	-169.6
	Well	Kitchen Sink	07/20/2009		14000	-314.7
	Well	Kitchen Sink	05/14/2009		17000	-187.4
	Well	Kitchen Sink	08/07/2009		18000	-298.3
	Well	Basement Pressure Tank	01/07/2010		18000	-205.7
	Well	Basement Pressure Tank	11/24/2009		19000	-206.1
	Well	KITCHEN SINK	03/04/2010		20000	-219
	Well	KITCHEN SINK	04/15/2010		20000	-224.5
	Well	KITCHEN FAUCET	10/26/2010		20000	-224.1
	Well	Kitchen Sink	11/24/2009		21000	-221.3
	Well	KITCHEN SINK	02/04/2010		21000	-203.8
	Well	KITCHEN SINK	08/26/2010		21000	-228.8
	Well	KITCHEN SINK	07/13/2010		22000	-246.5
	Well	KITCHEN SINK	09/10/2010		22000	111.4
	Well	Before Treatment System- Kit	11/05/2010		22000	-202
	Well	Kitchen Sink	12/10/2009		24000	-244
	well	BASEMENT AT PRESSURE	12/10/2009		24000	-219.5
	Well	Kitchen Sink	02/17/2009		25000	-132.8
	Well	Kitchen Sink	01/25/2009		26000	
	Well	KITCHEN SINK	06/03/2010		26000	-237.6
	Well	Before Treatment System	01/20/2011		26000	
	Well	VALVE FROM SHED	12/21/2010		< 590	91
			08/13/2008			
	Well	Kitchen Sink	10/25/2009			-235.2
	Well	Hydrant at Well Head	03/31/2010	< .025	.36	126.5
	Pond	Pond	03/31/2010	< .025	1.9	131
	well	Kitchen Sink Faucet	07/08/2010		.44	194.3
	Well	Kitchen Sink Faucet	03/16/2009		.57	148.7
	well	KITCHEN SINK	03/22/2010	< .025	2.1	117
	Well	Kitchen Sink Faucet	12/09/2010			149
	Well	Pressure Tank	02/08/2010		.39	133.8
			08/13/2009		150	45.6
			09/29/2010	< .01	158	
			03/17/2009		503	
	Well	Kitchen Sink	01/06/2009		600	
			05/28/2008			
			10/05/2008			
	well	Pressure Tank in Basement	12/14/2009		4.3	6.8
	Well	PRESSURE TANK	01/21/2010		250	121.3
			02/12/2009		.24	
			01/15/2009		< 7.92	
			10/15/2008			
			12/17/2008	< .01		
	Well	Basement Bathroom Sink	01/22/2009		< 7.92	
	Well	Kitchen Sink	10/26/2008			
			04/13/2010	< .01	0	
			04/27/2010	.362	0	
			08/24/2010	.01	0	
			08/24/2010	< .01	0	
			09/02/2010	< .01	0	
			09/15/2010	< .01	0	
			09/15/2010	< .0001	0	
	Well	AFTER TREATMENT	08/26/2010	< .025	.22	76
	well	OUTSIDE SPIGOT - PROVID	03/06/2010		.27	131.7

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
well	OUTSIDE SPIGOT - PROVIDE	02/02/2010		.6	149.7
Well	AFTER TREATMENT	09/02/2010	< .025	.67	143.1
Well	OUTSIDE FAUCET- PROVIDE	12/03/2009		.68	120.9
Well	After Treatment System in Sy	08/10/2011	.0066	.71	197.5
well	OUTSIDE SPIGOT - PROVIDE	01/07/2010		1.7	142.5
Well	AFTER TREATMENT	08/12/2010	< .025	1.7	136.5
Well	Kitchen Sink- Provided Water	11/12/2009		2.4	558.7
Well	After Treatment System in Sy	07/20/2011	.041	2.7	172
Well	BEFORE TREATMENT	09/02/2010	< .025	3	153.2
Well	FINAL EFFLUENT (AFTER T	08/06/2010	< .025	10	240.1
		09/08/2010	< .01	12.5	
		09/21/2010	< .01	15.3	
well	OUTSIDE SPIGOT, PROVIDE	04/25/2010		17	150.8
		07/15/2009	< .01	20.2	
Well	Before treatment	08/12/2010	< .025	21	155.5
Well	AFTER TREATMENT	09/09/2010	< .025	21	150.1
Well	Before Treatment System in S	10/18/2011	.0117	42	206.1
Well	Kitchen Sink	06/24/2009		52	
Well	After Treatment System in Sy	09/28/2011	.011	58	168.2
Well	Other (list)	10/27/2011	< .025	58	
Well	After Treatment System in Sy	11/08/2011	< .025	59	248
Well	After treatment in system she	03/24/2011	.0057	62	185.4
		08/18/2010	< .01	65.6	
Well	After Treatment in System Sh	05/10/2011	< .025	66	117.2
Well	Before Treatment System in S	08/10/2011	.007	72	187.9
Well	Before Treatment System in S	10/05/2011	.0097	75	338.1
well	AFTER TREATMENT	05/20/2010	< .025	78	172.4
Well	After Treatment	12/16/2010	.0055	79	152.8
		11/09/2010	< .01	80.4	
		08/31/2010	< .01	80.9	
Well	After Treatment System in Sy	08/03/2011	.018	81	141
Well	Other (list)	11/21/2011	< .025	82	237
Well	After Treatment	05/14/2010		90	
Well	After treatment in system she	02/03/2011	.0065	90	
Well	After Treatment In System Sh	08/17/2011	.01	96	174.1
Well	After Treatment in System Sh	05/31/2011	.0087	97	162.2
Well	After Treatment System in Sy	08/24/2011	.014	99	147
Well	After Treatment	10/13/2010	< .025	110	143.2
Well	After Treatment in System Sh	05/17/2011	.0088	110	157.2
Well	Before Treatment System in S	09/15/2011	.014	110	229.9
Well	After Treatment in System Sh	05/03/2011	.0095	120	187.5
Well	After Treatment in System Sh	06/07/2011	.0086	120	130.6
Well	Before Treatment System in S	07/20/2011	.01	120	172
Well	After Treatment System in Sy	08/31/2011	.016	130	146.9
Well	Other (list)	12/01/2011	.0075	130	217.8
Well	BEFORE TREATMENT	08/26/2010	< .025	140	111.3
Well	After treatment	07/13/2011	.01	140	293.7
Well	After Treatment System in Sy	11/03/2011	< .025	140	203.3
Well	After Treatment	05/14/2010		150	
Well	After Treatment	05/14/2010	< .025	150	
		06/09/2010	< .01	154	
Well	Kitchen Sink	05/14/2009		160	123.3
Well	AFTER TREATMENT	09/23/2010	< .025	160	154.9
Well	After Treatment in System Sh	04/26/2011	.008	160	154.7
Well	After treatment in system she	03/10/2011	.0042	170	140.3
Well	BEFORE TREATMENT	08/20/2010	< .025	200	109.2
Well	After Treatment in System Sh	04/19/2011	.0089	200	207.8
Well	After Treatment System in Sy	09/07/2011	.01	200	267.1
Well	After Treatment System in Sy	11/17/2011	< .025	210	211.1
Well	After treatment in system she	02/10/2011	.0044	220	160.6
Well	Before Treatment	07/13/2011	.0041	220	157.1
		10/21/2010	< .01	232	
Well	After Treatment System in Sy	10/11/2011	.0093	240	172.9
Well	After treatment in system she	04/05/2011	.0051	260	127.6
Well	AFTER TREATMENT	08/20/2010	< .025	270	92.3
Well	After treatment in system she	03/17/2011	.0057	270	165.8
Well	BEFORE TREATMENT	09/10/2010	< .025	280	87.8
Well	After Treatment in System Sh	09/21/2011	.0095	280	161
Well	Other (list)	12/01/2011	.005	280	228.5
Well	After Treatment in System Sh	05/24/2011	.0073	290	140.6
Well	AFTER TREATMENT	07/08/2010	< .025	300	170.8
Well	After Treatment in System Sh	07/06/2011	.013	300	240.8
Well	Kitchen Sink	04/14/2009		311	
Well	After treatment in system she	02/24/2011	.0066	330	148.1
Well	After treatment in system she	03/03/2011	.006	330	162.5
		07/08/2010	< .01	332	

land_owner
Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	well	BEFORE TREATMENT	07/08/2010	< .025	340	163
	Well	After Treatment	12/28/2010	.0047	350	144.8
	Well	At Pressure Tank in Water Tr	10/27/2011	< .025	350	
	Well	AFTER TREATMENT SYSTEM	11/12/2010	< .025	380	153.8
	Well	Kitchen Sink	07/20/2009		390	150.2
	Well	After Treatment in System Sh	06/21/2011	.0098	400	81.3
			07/21/2010	< .01	444	
			11/22/2010	< .01	454	
	Well	After treatment in system she	03/31/2011	.0028	470	153.9
	Well	AFTER TREATMENT SYSTEM	04/12/2011	.0033	480	208.2
	Well	AFTER TREATMENT	07/22/2010	< .025	490	83.2
	Well	After Treatment System in Sy	10/25/2011	< .005	510	184
	Well	After Treatment in System Sh	06/29/2011	.011	530	200.7
			07/21/2010	< .01	565	
	Well	After Treatment	07/15/2010	< .025	570	
			12/02/2010		578	
	Well	After Treatment System in Sy	10/05/2011	.015	590	357.8
	Well	After Treatment System	07/27/2011	.021	600	181
			12/07/2010	< .01	621	
	Well	Kitchen Sink	04/14/2009		640	
	Well	Kitchen Sink	09/15/2009		680	79.3
	well	AFTER SYSTEM	06/01/2010	< .025	720	137.6
	Well	BEFORE TREATMENT	10/08/2010	< .025	720	183.4
	Well	After Treatment in System Sh	06/14/2011	< .025	810	155.8
			10/12/2010	< .01	819	
	Well	Kitchen sink	08/13/2009		820	
	Well	AFTER TREATMENT	11/23/2010	< .025	840	160.2
	Well	AFTER TREATMENT	10/01/2010	< .025	880	128.8
			06/02/2010	< .01	896	
			06/24/2010	.027	902	
	Well	Before Treatment at Pressure	05/03/2011	.0041	910	218.3
	Well	After treatment in Treatment S	02/17/2011	.0063	960	178
	Well	After treatment	06/10/2010	< .025	1000	147.2
			10/21/2010	< .01	1020	
			10/28/2010	< .01	1140	
			07/13/2010	< .01	1190	
	Well	AFTER TREATMENT	11/20/2010	< .025	1200	157.5
	Well	AFTER TREATMENT	12/10/2010	.0052	1200	169.8
	Well	Other (list)	12/20/2011		1200	186.4
	well	BEFORE TREATMENT	05/14/2010	< .025	1300	
	Well	BEFORE TREATMENT	10/13/2010	< .025	1300	155.5
	Well	After Treatment	11/04/2010	< .025	1300	162.5
	Well	After Treatment	12/21/2010		1300	115.5
	Well	Before Treatment at Pressure	04/19/2011	.0053	1300	228
	Well	Before Treatment System in S	08/03/2011	.016	1300	165
			09/08/2010		1410	
			10/01/2009	< .01	1500	
	Well	After Treatment System in Sy	10/18/2011	.0148	1500	224.2
	Well	Before treatment	07/22/2010	< .025	1600	107.7
	well	AFTER TREATMENT	07/01/2010	< .025	1700	149.9
	Well	Pressure Tank	03/24/2011	< .0025	1700	205.9
	Well	Before Treatment at Pressure	04/26/2011	.0054	1800	171.9
	well	Kitchen Sink	06/24/2010	< .025	1900	
	Well	Before Treatment System in S	11/03/2011	< .025	2000	220.1
			09/21/2010	.057	2020	
			07/15/2009	< .01	2090	
	Well	After System Treatment	01/20/2011	.0073	2100	159.9
	Well	Holding Tank	04/14/2009		2200	
	well	AFTER SYSTEM	06/03/2010	< .025	2200	142.2
	Well	AFTER TREATMENT SYSTEM	12/02/2010		2200	214
	Well	Before Treatment in System S	08/24/2011	.019	2200	167
	Well	Basement	06/24/2009		2300	
	Well	Other (list)	12/08/2011		2300	160
			06/15/2010	< .01	2380	
	Well	After treatment in System She	01/06/2011	.0059	2500	164
	Well	Pressure Tank Before Treatm	07/06/2011	.0091	2500	200.2
	Well	Before Treatment System in S	10/11/2011	.013	2600	188
	Well	BEFORE SYSTEM	06/01/2010	< .025	2700	156.9
	Well	Before Treatment System in S	08/17/2011	.014	2700	201.8
	Well	Before Treatment System in S	11/17/2011	< .025	2700	227.1
	Well	BEFORE TREATMENT	09/23/2010	< .025	2800	187.2
	Well	Before Treatment System in S	10/25/2011	.009	2900	193.7
	Well	Before Treatment System in S	11/08/2011	< .025	2900	282.9
	well	HOSE AFTER SYSTEM	05/27/2010	< .025	3000	111.7
	Well	AFTER TREATMENT	06/17/2010	< .025	3000	148.3
	Well	Before Treatment	05/10/2011	< .0025	3000	124.7

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	Other (list)	11/21/2011	< .025	3000	247.7
		07/13/2010	< .01	3030	
		04/30/2009		3120	
		05/27/2010	< .01	3190	
Well	Pressure Tank	03/31/2011	.0053	3200	170
Well	Other (list)	01/05/2012		3200	165.9
Well	Before Treatment	07/15/2010	< .025	3300	
Well	After Treatment System in Sy	01/13/2011	.0055	3300	176.6
Well	Pressure Tank	03/17/2011	.0076	3300	179.9
Well	Pressure Tank	04/12/2011	< .0025	3300	223.3
Well	After treatment	10/08/2010	< .025	3700	164.2
Well	After Treatment System in Sy	09/15/2011	.022	3800	239.5
well	AFTER SYSTEM	06/14/2010	< .025	4100	145.8
		11/09/2010	< .01	4190	
Well	Before Treatment at Pressure	05/31/2011	.013	4300	195.5
Well	After treatment in system she	01/27/2011	.0072	4600	139.6
Well	BEFORE SYSTEM FROM HC	05/27/2010	< .025	4800	120.9
Well	Before Treatment	06/24/2010	< .025	4800	
		06/15/2010	< .01	5040	
Well	Before Treatment at Pressure	05/17/2011	.0077	5100	174
Well	Basement	05/14/2009		5200	140.2
Well	Before Treatment	11/20/2010	< .025	5200	167.9
Well	Pressure Tank	04/05/2011	.0043	5200	150.1
		03/17/2009		5620	
Well	Basement	08/13/2009		5700	
		06/24/2010	.012	5910	
well	BEFORE TREATMENT	06/17/2010	< .025	6100	162.8
Well	Before Treatment	10/20/2010	< .025	6100	165
Well	Basement	07/20/2009		6200	150.5
well	BEFORE TREATMENT	06/10/2010	< .025	6300	143.9
Well	Before Treatment System in S	09/28/2011	.019	6400	194.1
Well	AFTER TREATMENT	10/20/2010	< .025	6500	172.3
		05/27/2010	.012	6670	
Well	Pressure Tank	03/10/2011	.0099	6700	163.4
Well	Before Treatment System	07/27/2011	.0014	6700	201
Well	BEFORE TREATMENT SYS	10/03/2011	.0093	6800	
Well	BEFORE TREATMENT	10/28/2010	< .025	6900	166.3
Well	Before Treatment at Pressure	05/24/2011	.0098	6900	160.4
Well	Pressure Tank Before Treatm	06/21/2011	.011	7500	92.9
		01/12/2009		7990	
		12/02/2010	< .01	8230	
Well	Before Treatment System in S	08/31/2011	.016	8300	164.1
		12/07/2010	< .01	8370	
Well	Before Treatment at Pressure	06/07/2011	.0095	8400	138.1
Well	Before treatment	07/01/2010	< .025	8900	161.9
Well	Before Treatment	11/23/2010	< .025	9000	174.6
		10/28/2010	< .01	9360	
Well	Before Treatment System in S	09/21/2011	.022	9600	182
Well	Pressure Tank	02/24/2011	.008	9700	167.1
Well	Before Treatment	11/12/2010	< .025	10000	171.4
Well	Pressure Tank Before Treatm	06/29/2011	.006	10000	178.9
		10/12/2010	.012	10100	
		07/08/2010	< .01	10700	
Well	BEFORE TREATMENT	06/14/2010	< .025	11000	150.5
Well	BEFORE TREATMENT SYS	11/04/2010	< .025	11000	174.7
Well	Before Treatment	12/02/2010		11000	219.1
Well	Before Treatment	12/10/2010	.0069	11000	177.2
Well	Before Treatment	12/21/2010		11000	123.2
Well	Before Treatment System in S	01/06/2011	.0057	11000	157.8
Well	Before Treatment System in S	09/07/2011	.02	11000	267.1
		06/02/2010	< .01	11100	
		04/30/2009		11800	
		11/02/2010	< .01	11900	
Well	Before Treatment at Pressure	06/14/2011	< .025	12000	173.1
Well	Basement	09/15/2009		13000	79.3
Well	Before treatment	06/03/2010	< .025	13000	149.4
Well	Before Treatment in System S	01/13/2011	.0055	13000	163.8
Well	Before treatment in system sh	02/10/2011	.006	14000	166.9
		01/29/2009		14200	
Well	Kitchen Sink	02/12/2009		15000	
		10/01/2009	.01	16000	
Well	Pressure Tank- Before treatm	02/17/2011	.006	16000	185.6
Well	Before Treatment	10/01/2010	< .025	17000	147.3
Well	Before Treatment in System S	12/28/2010	.0052	17000	162.8
Well	BEFORE TREATMENT SYS	01/20/2011	.0057	17000	157
Well	Before treatment in system sh	01/27/2011	.0064	17000	147.3

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	Before Treatment in System	02/03/2011	.0063	18000	
	Well	Kitchen Sink	01/22/2009		19000	
			11/02/2010		24600	
	Well	Holding Tank	04/14/2009		< 7.9	
	Well	BEFORE TREATMENT SYSTEM	12/16/2010	.0081	< 8700	175.6
			07/17/2008			
	Well	Kitchen Sink	11/10/2008			
			11/19/2008			
			12/16/2008	< .01		
			12/16/2008			
	Well	HOSE OUTSIDE (WELL)	05/10/2010			
	Well	Basement before treatment system	05/20/2010			
			07/28/2010	< .01		
			08/18/2010	< .01		
			09/08/2010	< .01		
	Spring	Pipe out of Spring	03/25/2009		.16	202.7
			04/05/2010		< .1	100.2
			02/04/2009		< 7.92	
	Well	Bathroom Sink	02/24/2011		1.7	162
	Well	Kitchen Sink	11/09/2009		3.3	243.3
	Well	Pressure Tank	11/09/2009		4.2	220.8
			10/26/2009		15.1	
			05/10/2010		< 7.92	
	Well	Kitchen Sink After Treatment	05/10/2011		.55	115.2
	Well	Kitchen Sink After Treatment	05/31/2011		1.1	142
	Well	After RO	06/14/2011		1.2	147.8
	Well	Kitchen Sink After Treatment	06/29/2011		1.2	170.1
	Well	Kitchen Sink After RO System	08/17/2011		1.2	218.8
	Well	Pressure Tank in Shed Before	06/07/2011		1.3	139.4
	Well	Kitchen Sink After RO Treatment	08/24/2011		1.3	170
	Well	Kitchen Sink After RO Treatment	10/05/2011		1.3	279.1
	Well	Kitchen Sink After Treatment	06/21/2011		1.4	92.8
	Well	Kitchen Sink After Treatment	07/06/2011		1.5	103.1
	Well	Kitchen Sink After RO Treatment	10/11/2011		1.5	186.9
	Well	Kitchen Sink After Treatment	05/17/2011		1.6	139
	Well	Kitchen Sink After Treatment	07/13/2011		1.6	239.3
	Well	Kitchen Sink After RO Treatment	07/27/2011		1.6	214
	Well	Kitchen Sink After Treatment	05/24/2011		1.7	130.8
	Well	Kitchen Sink After RO Treatment	09/07/2011		1.7	259.4
	Well	After RO	02/17/2011		1.8	156.8
	Well	Kitchen Sink After RO System	07/20/2011		1.8	215
	Well	RO System Kitchen Sink	03/03/2011		1.9	132.1
	Well	RO Kitchen	03/24/2011		1.9	171.4
	Well	Kitchen Sink After RO Treatment	08/10/2011		1.9	198
	Well	Kitchen Sink After RO Treatment	09/21/2011		1.9	180
	Well	RO Kitchen Sink	02/24/2011		2	104.1
	Well	Kitchen Sink After Treatment	05/03/2011		2	167.1
	Well	After RO Treatment System a	10/18/2011		2	223.7
	Well	Kitchen Sink After Treatment	03/17/2011		2.1	124.4
	Well	Kitchen Sink After Treatment	09/07/2011		2.1	245.2
	Well	Kitchen Sink After Treatment	02/10/2011		2.4	136
	Well	Kitchen Sink After RO Treatment	08/31/2011		2.5	196
	Well	Kitchen Sink After Treatment	05/10/2011		3	127
	Well	Kitchen Sink After Treatment	09/21/2011		3	157
	Well	After RO System	02/03/2011		3.1	107.9
	Well	Kitchen Sink After RO Treatment	09/30/2011		3.1	256.8
	Well	RO Faucet	12/21/2010		3.4	83.1
	Well	Kitchen Sink After RO Treatment	09/15/2011		3.7	233.1
	Well	Kitchen Sink After Treatment	09/30/2011		4	248.6
	Well	Kitchen Sink After Treatment	05/24/2011		4.2	143
	Well	Kitchen Sink After Treatment	07/27/2011		4.4	197
	Well	After RO	01/27/2011		4.5	110
	Well	Kitchen Sink After Treatment	07/13/2011		5.3	167.7
	Well	Kitchen Sink After Treatment	03/17/2011		5.5	170.8
	Well	Kitchen Sink After Treatment	06/14/2011		6.5	138.7
	Well	After RO Treatment System a	10/25/2011		6.8	200
	Well	After RO Treatment System in	11/03/2011		6.8	217
	Well	Kitchen Sink After Treatment	06/29/2011		7.1	169
	Well	RO System	12/09/2010		7.3	119.3
	Well	Kitchen RO System	01/20/2011		7.3	118.4
	Well	Kitchen Sink After Treatment	06/21/2011		7.3	82.2
	Well	After Treatment System in Kit	11/17/2011		7.8	219.5
	Well	After Treatment System Kitch	01/27/2011		9.6	133.1
	Well	After RO Treatment System in	11/08/2011		9.6	248
	Well	Kitchen Sink After Treatment	05/17/2011		10	150.7
	Well	Kitchen Sink After Treatment	08/17/2011		11	189.5

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	After Treatment System	02/17/2011		13	155.5
Well	Kitchen Sink After Treatment	05/03/2011		13	185.7
Well	After Treatment System at Kit	10/18/2011		13	211.6
Well	After Reverse Osmosis	12/01/2011		13	219.6
Well	After Treatment System	12/09/2010		14	162.1
Well	RO System	01/13/2011		14	126.6
Well	Kitchen Sink After Treatment	08/03/2011		14	148
Well	RO System - Kitchen Sink	12/16/2010		16	117.1
Well	Kitchen Sink After Treatment	04/26/2011		16	128.3
Well	After RO Treatment System in	11/17/2011		16	205.1
Well	Kitchen Sink After Treatment	10/05/2011		17	275
Well	After Reverse Osmosis	11/21/2011		18	204.4
Well	Kitchen Sink After Treatment	09/15/2011		20	214.9
Well	Kitchen Sink After Treatment	04/19/2011		21	192
Well	RO System Kitchen Sink	12/28/2010		22	111.3
Well	Kitchen Sink RO System	01/06/2011		24	117.6
Well	Kitchen Sink After Treatment	01/13/2011		24	171.7
Well	Kitchen Sink After Treatment	10/11/2011		26	180
Well	Kitchen Sink After Treatment	07/06/2011		28	137.6
Well	After RO	03/31/2011		31	161.6
Well	Pressure Tank in Shed Before	04/12/2011		31	193.7
Well	Kitchen Sink After Treatment	02/03/2011		33	124.5
Well	Kitchen Sink After Treatment	03/03/2011		36	180.6
Well	Kitchen Sink After Treatment	04/05/2011		36	148.7
Well	Kitchen Sink After Treatment	12/16/2010		40	154.4
Well	Kitchen Sink Faucet	11/21/2011		41	239
Well	Kitchen Sink Faucet	12/01/2011		42	231.2
Well	Kitchen Sink After Treatment	01/06/2011		43	170.9
Well	Kitchen After Treatment Syste	01/20/2011		44	150.6
Well	RO System	12/02/2010		48	190.9
Well	Kitchen Sink After Treatment	07/20/2011		48	366
Well	Kitchen Sink After Treatment	02/10/2011		49	149.9
Well	After Treatment System in Kit	11/08/2011		49	255.3
Well	Kitchen Sink Final Effluent	12/02/2010		51	204.7
Well	Kitchen Sink After Treatment	05/31/2011		51	146
Well	Kitchen Sink After Treatment	08/31/2011		54	186
Well	After Treatment System at Kit	10/25/2011		54	201.3
Well	Kitchen Sink After Treatment	04/26/2011		55	159.2
Well	Kitchen Sink After Treatment	06/07/2011		57	125.4
Well	After Treatment System in Kit	11/03/2011		75	221.6
Well	Kitchen Sink After Treatment	02/24/2011		78	140.9
Well	Effluent from Kitchen Faucet	11/20/2010		86	151.7
Well	Kitchen Sink After Treatment	08/10/2011		87	238
Well	Effluent from Kitchen Faucet	11/23/2010		93	150.2
Well	Effluent Kitchen Faucet	11/01/2010		110	148
Well	Effluent from Kitchen	12/21/2010		120	113
Well	Kitchen Sink After Treatment	04/12/2011		130	177.9
Well	Kitchen Sink After Treatment	04/19/2011		130	210
Well	Kitchen Sink After Treatment	04/05/2011		140	164.7
Well	RO Faucet	11/23/2010		150	113.8
Well	Kitchen Sink After Treatment	12/28/2010		150	145.3
Well	Kitchen Sink After Treatment	08/24/2011		170	156
Well	Effluent	10/02/2010	< .025	290	132.7
Well	RO Faucet	11/20/2010		410	85.3
Well	BEFORE TREATMENT SYSTEM	01/20/2011		1100	
Well	Influent at Hydrant	11/01/2010		2500	121.7
Well	Midpoint After 1st Tank Before	10/02/2010		2900	103.4
Well	Before Treatment System in S	08/24/2011		4100	-37
Well	Before Treatment System at F	06/14/2011		4400	108.8
Well	Before Treatment System in S	07/27/2011		4500	-67
Well	Before Treatment System in S	08/31/2011		4800	-40.8
Well	Pressure Tank in Shed Before	05/17/2011		4900	111.2
Well	Before Treatment System in S	08/17/2011		4900	-7.2
Well	Before Treatment System in S	08/10/2011		5100	13.7
Well	Pressure Tank in Shed Before	06/07/2011		5500	74.5
Well	Pressure Tank in Shed Before	05/24/2011		5900	29.7
Well	Before Treatment System in S	09/30/2011		6200	4.9
Well	Pressure Tank in Shed Before	07/06/2011		6600	-64
Well	Pressure Tank in Shed Before	04/19/2011		6700	141.4
Well	Before Treatment System in S	07/20/2011		6800	114
Well	Before Treatment Pressure T	04/05/2011		7200	-21
Well	Pressure Tank in Shed Before	06/29/2011		7200	175.2
Well	Pressure Tank in Shed Before	04/12/2011		7400	136.2
Well	Pressure Tank in Shed Before	06/21/2011		7500	-76.4
Well	Pressure Tank in Shed Before	07/13/2011		7500	239.5
Well	At Pressure Tank in Water Tr	12/01/2011		7600	141.3

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Well	Before Treatment System in S	08/03/2011		7700	-26
	Well	At Pressure Tank in Water Tr	11/21/2011		7900	145.1
	Well	Before Treatment System in S	09/21/2011		8000	51
	Well	Pressure Tank in Shed Before	05/03/2011		8100	175.5
	Well	Before Treatment System in S	11/03/2011		8100	122.6
	Well	Before Treatment System Pre	03/24/2011		8400	95.5
	Well	Before Treatment System at F	03/31/2011		8500	126.8
	Well	Pressure Tank in Shed Before	05/31/2011		8600	81.3
	Well	Before Treatment System in S	10/05/2011		8600	173.1
	Well	Before Treatment System in S	10/11/2011		8600	36.2
	Well	Before Treatment System in S	10/18/2011		8600	-.2
	Well	Before Treatment System in S	11/08/2011		8600	69.1
	Well	Before Treatment System in S	10/25/2011		8700	5.3
	Well	Before Treatment System in S	09/15/2011		8800	-30.1
	Tank	Kitchen Sink Water Provided	11/01/2010		9400	103.4
	Well	Before Treatment System in S	09/07/2011		9500	-16.5
	Well	Pressure Tank in Shed Before	04/26/2011		9600	151.6
	Well	Pressure Tank in Shed Before	05/10/2011		9700	17.5
	Well	Before Treatment System in S	11/17/2011		11000	280.1
			08/18/2010	.076	11900	
	Well	Kitchen Sink	09/10/2010	.065	16000	23.3
			11/24/2009	.07	18000	
	Well	Influent	10/02/2010	.063	18000	-32.1
	Well	KITCHEN SINK	01/05/2010		23000	144.9
			07/13/2010		23000	-162.1
			12/21/2009	.074	29100	
			04/12/2011			141.3
			04/08/2009		.55	199.7
	Well	Pressure Tank	08/30/2010	.12		179.5
	Well	Hand Dug Well	10/26/2010	.12		198.6
	Spring	Kitchen Sink Faucet	11/30/2009	.15		127.6
	Spring	Kitchen Sink Faucet	03/25/2009	.18		264.1
	spring	Spring House	11/30/2009	1.2		123.9
	Spring	Water Well	06/16/2008			
	Spring	Kitchen	09/19/2008			
	Spring	Unknown	10/16/2008			
	Spring	KITCHEN SINK	12/16/2009	< .1		196.6
	Well	Old Dug Well - Canteen	06/24/2009	.4		162.9
	Well	Kitchen Sink	06/04/2010	20		85
	Well	Kitchen Sink	06/24/2009	27		241.3
	Well	Basement Sink	02/01/2010	3.5		159.8
	Well	Kitchen Sink	11/23/2009	6.8		103.5
	Well	Basement at Pressure Tank	11/23/2009	12		125.7
	well	BASEMENT AT PRESSURE	01/31/2010	.11		194
			11/18/2010	< .01	0	
	Well	Kitchen Sink	01/25/2009	.37		
			08/07/2009	.92		
	Well	Kitchen Sink	02/17/2009	1.4		88.4
			08/13/2008			
			10/26/2009			
	Well	Kitchen Sink	09/10/2010	.14		142.7
	Well	Kitchen Sink	12/14/2010	.15		153.2
	Well	Pressure Tank	04/01/2010	< .025	.33	141.1
	Lake	Lake	04/01/2010	.081	4.4	112
	Pond	Pond	09/10/2010		15	139.6
	Well	Pressure Tank	08/19/2010	.38		111.4
	Well	Pressure Tank	01/06/2011			
	Well	Basement - Before System	02/26/2009		1.5	107.5
	Well	Pressure Tank	01/24/2010		1.5	104.5
	Well	Kitchen Sink- After Softener	11/09/2008			
	Well	Pressure Tank	11/06/2010	.091		195.5
	well	Pressure Tank	03/18/2010	< .025	35	151.2
	Well	Kitchen Sink Faucet	11/05/2009		84	142.2
	Well	OUTSIDE FAUCET	11/05/2009		94	141.4
	Well	Kitchen Sink	01/21/2010		.52	163.2
	Tank	KITCHEN SINK- PROVIDED	06/17/2010		.14	175.2
	Tank	KITCHEN SINK-PROVIDED	02/02/2010		.17	190.9
	Tank	KITCHEN SINK- PROVIDED	05/22/2010		.2	194.4
	Tank	KITCHEN SINK - PROVIDED	04/24/2010		.23	234.7
	Tank	PROVIDED WATER AT KITCH	12/20/2010		.26	210.4
	Tank	KITCHEN SINK-PROVIDED	01/11/2010		.34	173.6
	Tank	KITCHEN SINK-PROVIDED	11/30/2009		.4	199.3
	Tank	KITCHEN SINK-PROVIDED	12/16/2009		1.1	207.8
	Tank	KITCHEN SINK - PROVIDED	10/26/2010		1.1	215.4
	Tank	KITCHEN SINK - PROVIDED	03/06/2010		1.2	195
	Tank	KITCHEN SINK PROVIDED	09/23/2010		1.4	181.9

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Tank	KITCHEN SINK - PROVIDED	07/28/2010		2.8	152.9
			11/02/2010	.062	548	
	Well	Kitchen Sink Faucet	06/14/2009		12000	-237.2
	Well	Kitchen Sink Faucet	02/17/2009		15000	94.2
	Well	Kitchen Sink Faucet	05/14/2009		15000	-149.1
	Well	Kitchen Sink Faucet	01/25/2009		17000	
			10/12/2010	.057	18400	
	Well	Outside Faucet	07/20/2011		19300	
	Well	Kitchen Sink Faucet	07/22/2009		23000	-64.9
			10/26/2010	.066	24700	
			09/16/2010	.051	25400	
	Well	Outside Faucet	08/11/2011		26100	
			10/19/2010	.063	26500	
			09/30/2010	.057	27600	
		NOT INDICATED	08/13/2009		29300	
			11/08/2010	.065	31000	
			11/22/2010	.069	31100	
	well	PRESSURE TANK	10/29/2009		32000	-195.1
	Well	Kitchen Sink Faucet	07/20/2009		34000	-215.6
	Well	Kitchen Sink Faucet	09/21/2009		34000	-276.6
	Well	Kitchen Sink Faucet	08/07/2009		37000	-222.4
	Well	Kitchen Sink Faucet	10/29/2009		39000	-213.1
			12/08/2010	.076	39600	
			08/11/2008			
	Well	At Spring House	03/16/2010		1.9	190.1
	Pond	Pond at Dock	04/05/2010		30	111.7
	Well	After- Treatment Shed	05/31/2011		3.6	121.1
	Well	After Treatment System in Sy	09/21/2011		5.7	139
			06/07/2011		14	98.3
	Well	After- Treatment shed	05/10/2011		26	63.6
	Well	After- Treatment Shed	05/24/2011		26	87.2
	Well	Effluent from Valve in Shed	03/24/2011		30	139.5
	Well	After Treatment in System Sh	07/06/2011		37	190.1
	Well	After Treatment in System Sh	01/13/2011		39	
	Well	After Treatment in System Sh	01/06/2011		40	113.4
	Well	AFTER TREATMENT IN SYS	02/03/2011		49	134.9
	Well	After treatment in treatment s	04/05/2011		49	94.6
	Well	After- Treatment Shed	05/17/2011		50	134.1
	Well	After Treatment in System Sh	03/10/2011		51	149.3
	Well	AfterTreatment- Treatment Sh	07/13/2011		63	238.5
	Well	In Treatment System Shed Af	12/01/2011		72	205.3
	Well	After- Treatment Shed	04/26/2011		73	157.9
	Well	After- Treatment Shed	05/03/2011		73	186.4
	Well	After Treatment System in Sy	10/05/2011		73	313.1
	Well	After Treatment in System Sh	03/17/2011		83	149.1
	Well	After Treatment in System Sh	03/03/2011		85	135.1
	Well	AFTER TREATMENT IN SYS	01/20/2011		87	145.3
	Well	After- Treatment Shed	11/03/2011		94	260
	Well	AFTER TREATMENT IN SYS	12/28/2010		96	130.4
	Well	In Treatment System Shed Af	11/21/2011		97	177.6
	Well	After Treatment in System Sh	02/10/2011		100	159.7
	Well	After Treatment System in Sy	09/28/2011		100	70.2
	Well	In system shed- after treatme	07/27/2011		110	159
	Well	After Treatment System in Sy	09/07/2011		110	275.2
	Well	AFTER TREATMENT	12/02/2010		120	213.3
	Well	After Treatment System	08/10/2011		120	228.1
	Well	After-Treatment Shed	10/25/2011		120	203
	Well	After- System Shed	10/18/2011		130	142.9
	Well	EFFLUENT FROM VALVE IN	12/21/2010		140	128.9
	Well	After Treatment in Treatment	04/19/2011		140	173.6
	Well	After- Treatment Shed	06/14/2011		140	115.7
	Well	After- Treatment Shed	11/08/2011		140	156.9
	Well	after treatment system in syst	11/17/2011		140	132.7
	Well	After treatment in system she	03/31/2011		150	142.7
	Well	After- Treatment Shed	06/21/2011		150	16.1
	Well	After Treatment System in Sy	08/17/2011		150	112.1
	Well	After Treatment System in Sy	08/24/2011		150	140
	Well	After Treatment System	08/31/2011		150	90.8
	Well	After- Treatment Shed	10/11/2011		150	149.8
	Well	After Treatment in Treatment	07/20/2011		160	125
	Well	After Treatment in System Sh	02/17/2011		170	131.8
			06/29/2011		170	127.6
	Well	After Treatment System in Sy	09/15/2011		170	65
	Well	After Treatment in System Sh	01/27/2011		190	201
	Well	After treatment in system she	04/12/2011		190	141.3
	Well	After Treatment System in Sy	08/03/2011		190	90

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	After Treatment in System Sh	02/24/2011		210	157.2
Well	AFTER TREATMENT SYSTE	12/09/2010		330	177.1
Well	AFTER TREATMENT	12/16/2010		350	141.1
Well	After treatment	11/13/2010		450	
Well	EFFLUENT FROM VALVE IN	11/20/2010		470	153.9
Well	EFFLUENT FROM VALVE IN	11/23/2010		530	157.8
Well	After Treatment-Portable Sys	10/14/2010	.17	1100	103.5
Well	Mid-Point in Treatment Syste	11/13/2010		3500	
Well	Kitchen Sink Faucet	02/17/2009		3800	125.8
		07/20/2009		4400	-100.8
Well	Pressure Tank	07/20/2009		4400	-100.8
Well	Pressure Tank	06/14/2009		4900	30.6
Well	Mid-Point in Treatment Syste	10/14/2010		4900	
Well	Pressure Tank	05/27/2009		6000	646.3
Well	Before- Treatment Shed	05/10/2011		7400	-58.4
Well	Before Treatment in System S	04/26/2011		7500	126.5
Well	Before- Treatment Shed	06/21/2011		7500	-99.9
Well	Before Treatment System in S	10/11/2011		8200	-24.3
Well	Before- Treatment Shed	05/24/2011		8400	-37.7
Well	Before Treatment System in S	07/20/2011		8600	-25
Well	Before- Treatment Shed	06/07/2011		9000	95.2
Well	Before Treatment in treatmen	04/12/2011		9200	143.2
Well	Before Treatment in System S	03/17/2011		9400	125.3
Well	Before Treatment in Treatmer	07/06/2011		9900	-23.7
Well	Before Pressure Tank and Be	12/20/2011		11000	52.2
		06/16/2010	.173	11600	
Well	Before Treatment in system s	02/03/2011		12000	40.5
Well	Before Treatment System in S	08/03/2011		12000	-87
Well	Before Treatment System in S	09/15/2011		12000	-.7
Well	Before Treatment System in S	10/25/2011		12000	25.8
Well	Before- Treatment Shed	11/08/2011		12000	87.7
Well	Before Pressure Tank and Be	11/21/2011		12000	-7.3
Well	Before Pressure Tank and Be	12/08/2011		12000	56.2
Well	Before Treatment System in S	08/17/2011		13000	-56.7
Well	Before Treatment System in S	08/31/2011		13000	-23.1
Well	Before Treatment System in S	09/28/2011		13000	-56.3
Well	Before Pressure Tank and Be	01/05/2012		13000	68.9
Well	Before Treatment in System S	02/17/2011		16000	113
Well	PRESSURE TANK	06/04/2010		17000	-33.2
Well	Before Treatment System	01/20/2011		17000	
Well	Before Treatment in System S	03/03/2011		17000	96.9
Well	Before Treatment in System S	03/31/2011		17000	167.1
Well	BEFORE - Basement at Pres	10/14/2010	.164	20000	11.2
Well	Before Treatment	11/13/2010		20000	
Well	PRESSURE TANK	09/08/2010		21000	37.5
well	PRESSURE TANK- BEFORE	12/03/2009		22000	-137.4
Well	PRESSURE TANK - BEFORE	03/06/2010		22000	158.7
Well	PRESSURE TANK	07/15/2010		22000	17.7
Well	Kitchen Sink	10/25/2009		24000	28.1
Well	BASEMENT AT PRESSURE	08/25/2010		25000	54.3
well	BASEMENT AT PRESSURE	02/02/2010		27000	74.6
Well	PRESSURE TANK- BEFORE	01/07/2010		28000	-136.8
Well	BASEMENT AT PRESSURE	04/25/2010		28000	90.6
		10/26/2009	.192	29700	
		09/15/2009		30000	-94.4
		09/30/2010	.201	31000	
Well	Kitchen Sink Faucet	12/03/2009		32000	78.2
well	BASEMENT AT PRESSURE	11/23/2009		33000	-145.2
		08/07/2009	.381	35000	
Well	Kitchen Sink Faucet	11/23/2009		36000	76
		08/11/2008			
Well	Pressure Tank in Basement	10/25/2009			-156.5
Well	PRESSURE TANK	09/10/2010	.16		126.7
Well	Kitchen Sink	02/17/2009		8.2	100.7
		02/10/2009		< 7.92	
Well	Well	07/17/2008			
		04/19/2010	< .01		
		04/27/2010	.013	0	
		06/09/2010	< .01	0	
		07/13/2010	< .01	0	
		07/29/2010	.011	0	
		08/04/2010	< .01	0	
		09/08/2010	< .01	0	
		10/12/2010		0	
		10/19/2010	< .01	0	
		10/26/2010	< .01	0	

Ex. 6 -- Personal Privacy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
			11/08/2010	< .01	0	
			11/15/2010	< .01	0	
	Tank	HOLDING TANK-PROVIDED	07/27/2010		.2	225.7
	Tank	PROVIDED WATER, AT HOL	05/22/2010		.26	213.8
	Tank	PROVIDED WATER, AT HOL	06/24/2010		.44	209.3
	Tank	Provided Water	03/16/2010		1.4	188.6
	Tank	KITCHEN SINK PROVIDED	02/02/2010		2.2	154.3
	Tank	KITCHEN SINK PROVIDED	01/04/2010		2.8	215.9
	Well	Provided Water	09/29/2010		2.9	104.1
			08/24/2010	.016	9.04	
	Tank	KITCHEN SINK - PROVIDED	11/09/2009		9.4	534.3
			10/07/2010		11.6	
			10/07/2010	< .01	11.6	
			09/15/2010	< .01	15.6	
			08/31/2010	< .1	15.7	
			12/07/2010	.01	19.6	
	Well	Well	10/25/2011		31.7	
			05/27/2010	.014	66.7	
			06/24/2010	< .01	447	
			04/30/2009		610	
	Well	Other (list)	12/14/2011		712	
	Well	Bathroom Sink	08/17/2009		1200	
	well	BATHROOM SINK AFTER TR	10/25/2009		1200	401.6
			07/06/2010	< .01	1210	
			10/21/2009	< .01	1320	
	Well	Bathroom Sink	05/13/2009		1400	
	Well	Bathroom Sink Faucet on First	07/20/2009		1500	397.7
	Well	Bathroom Sink	09/21/2009		1500	6.1
			07/21/2010	< .01	1740	
	Well	Bathroom Sink	09/29/2009		1800	
			06/15/2010	.011	2210	
	Well	Bathroom Sink	06/20/2009		2900	696.7
			07/15/2009	< .01	2980	
	Well	Bathroom Sink	10/12/2009		3600	440.1
			08/11/2010	< .01	4450	
	Well	Bathroom Sink	04/14/2009		6400	
			04/14/2009		6480	
			04/13/2010	.048	10600	
			07/15/2009	.043	10800	
	Well	Pressure Tank	10/25/2009		11000	656.4
	Well	Other (List)	06/20/2009		12000	
			04/30/2009		12600	
	Well	Basement Before Water Treat	04/14/2009		13000	
	Well	Other (List)	05/13/2009		13000	
	Well	Pressure Tank	07/20/2009		14000	643.8
			10/21/2009	.033	14100	
			04/14/2009		14400	
	Well	Pressure Tank	10/12/2009		15000	
	Well	Pressure Tank	08/17/2009		16000	
	Well	Pressure Tank	09/21/2009		17000	6.1
			01/12/2009		17600	
	Well	Pressure Tank	09/29/2009		18000	
			01/29/2009		18200	
			01/29/2009		18200	
			02/23/2009		18600	
			03/26/2009	.628	19600	
			02/04/2010	.11	19900	
	Well	Pressure Tank	02/12/2009		21000	
	Well	Other (List)	01/22/2009		23000	
			11/22/2010	< .01	29400	
	Well	Outside Faucet	07/20/2011		< 26	
	Well	Outside Faucet	08/09/2011		< 26	
			07/17/2008			
	Well	Post Drill	09/12/2008			
			09/18/2008			
	Well	Post Drill Well	09/18/2008			
	Well	Kitchen Sink	09/18/2008			
	Well	Hose Directly from Well	09/23/2008			
	Well	Outside/Well	10/01/2008			
	Well	After Treatment	10/13/2008			
	Well	Before Treatment at Holding	10/15/2008			
	Well	After Treatment Bypass Softn	10/15/2008			
	Well	Kitchen Sink After Treatment	11/09/2008			
			11/19/2008			
			11/19/2008			
			12/16/2008			

Ex. 6 -- Personal Privcy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
			12/16/2008			
			02/13/2009			
			03/26/2009	< .01		
			08/18/2010	< .01		
			09/16/2010			
			09/22/2010			
			09/29/2010	1.737		
			09/29/2010			
			11/02/2010	.01		
			01/27/2009		0	
Well		Kitchen Sink	03/12/2009		.86	94.2
			07/17/2008			
Well		Kitchen Sink	06/29/2011		.58	177.3
Well		Kitchen Sink Faucet	11/21/2011		.65	239.9
Well		Kitchen Sink	08/31/2011		3.1	119.9
Well		Kitchen Sink	05/31/2011		3.5	178.7
Well		Kitchen Sink	10/25/2011		4.3	330.2
Well		Kitchen Sink	07/27/2011		4.4	180
Well		Pressure Tank	03/06/2010		6.1	96.9
			04/13/2010	.013	7.87	
Well		Kitchen Sink	06/04/2010		10	96
			04/19/2010		30	117.9
Well		Kitchen Sink	09/21/2011		34	143
Well		Kitchen Sink	04/26/2011		56	156.6
			01/20/2009		618	
Well		Pressure Tank	07/29/2010		740	129.4
well		Pressure Tank	02/04/2010		940	146.4
Well		Kitchen Sink	05/13/2009		1200	
Well			04/01/2009		1300	175.1
Well		Kitchen Sink	01/09/2011		1500	155.8
Well		Pressure Tank	08/26/2010		1600	130.4
Well		Kitchen Sink	07/20/2009		1700	15.8
Well		Pressure Tank	09/08/2010		1700	129.7
Well		Kitchen Sink	02/04/2010		1800	144.7
Well		Kitchen Sink	02/24/2011		2100	107.1
Well		Kitchen Sink	06/20/2009		2200	91
Well		Kitchen Sink	08/17/2009		2600	
Well		Kitchen Sink	12/21/2010		2700	145.3
Well		Kitchen Sink	11/29/2010		3100	158.7
Well		Kitchen Sink	10/26/2010		3500	144.1
Well		Pressure Tank in Basement	01/04/2010		5200	169.7
Well		Pressure Tank	10/25/2009		5300	332.4
			09/15/2009		5500	102.8
well		Pressure Tank in Basement	12/03/2009		6000	100.4
Well		Kitchen Sink	12/03/2009		6600	99.7
Well		Pressure Tank	11/23/2009		7800	70.9
well		Kitchen Sink	11/23/2009		8300	60.8
Well		Kitchen Sink	09/21/2008			
Well		Kitchen Sink	10/25/2009			367.5
			11/19/2011			
Tank		Kitchen Sink - Provided Water	03/07/2010		3.3	160
			01/28/2010	.249	10.7	
			01/26/2009		395	
			03/09/2009		396	
Pond		Pond	01/06/2009		640	
Well		Basement Kitchen Sink	01/06/2009		700	
Well		Outside Faucet	09/15/2011		1610	
Well		Pressure tank	12/15/2011		1850	
well		KITCHEN SINK - 1ST FLOOR	10/30/2009		2000	57.8
			08/13/2009	.026	2020	
Well		Outside Faucet	10/27/2011		2120	
Well		Outside Faucet	08/11/2011		2630	
			06/24/2009	< .02	2710	
Well		Kitchen Sink Faucet	05/14/2009		2800	
			07/20/2011		2930	
			01/05/2010	.21	5050	
well		KITCHEN SINK	01/05/2010		6100	123.5
			10/28/2010	.074	9050	
			10/21/2010	.072	11400	
			10/04/2010	.171	13000	
			08/24/2010	.212	14300	
			05/28/2008	< .01		
			09/14/2008			
			12/17/2008	.016		
			01/05/2009			
well		FIRST FLOOR KITCHEN SINK	11/09/2009			104.9

Ex. 6 -- Personal Privcy

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
	Spring	Kitchen Sink	08/06/2009		.12	
	Spring	OUTSIDE SPIGOT	06/24/2010		.12	187.7
	Spring	KITCHEN FAUCET	12/21/2010		.12	185.2
	Spring	KITCHEN SINK	08/30/2010		.13	191.8
	Spring	KITCHEN SINK	09/21/2010		.16	195.6
	Spring	KITCHEN FAUCET	01/07/2011		.19	206.8
	Spring	Kitchen Sink	01/07/2010		.2	148.7
	Spring	Kitchen Sink	10/25/2011		.28	354.5
	Spring	Kitchen Faucet	05/31/2011		.29	224
	Spring	Outside Spigot	08/31/2011		.33	110.3
	Spring	Kitchen Sink	04/26/2011		.36	243.2
	Spring	KITCHEN SINK	07/27/2011		.66	209
	Spring	kitchen sink	03/19/2009		1.1	195.6
	Spring	Spring House	12/10/2009		4.7	117.8
	Spring	Kitchen Sink	12/10/2009		6.8	115.1
	Spring		09/28/2011		7.5	198.9
	Spring	Spring House	09/29/2009		9.3	317.8
	Spring	Kitchen Sink	02/04/2010		< .1	176.5
	Spring	Kitchen Sink	03/11/2010		< .1	169.3
	Spring	Kitchen Sink	04/19/2010		< .1	147.9
	Spring	Kitchen Sink	05/22/2010		< .1	208.4
	Spring	KITCHEN SINK	07/27/2010		< .1	223
	Spring	KITCHEN SINK	11/04/2010		< .1	205
			11/21/2011		< .1	285.7
			06/24/2008			
	Spring	Kitchen Sink	09/19/2008			
	Spring	Pipe into Pond	09/19/2008			
	Spring	Far end of Pond	09/19/2008			
	Spring		10/09/2008			
	Spring		10/16/2008			
	Spring		10/16/2008			
	Spring	Spring House	10/16/2008			
	Spring		10/16/2008			
			11/19/2011			
			10/16/2008	< .01	0	
	Well	Outside Spigot	01/24/2010		< 1.7	153.8
	Well	Kitchen Sink	01/24/2010		1.7	153.8
			08/10/2011		5100	13.7
	Well	Utility Room Sink	06/07/2009		.43	156.7
			02/04/2009		< 7.92	
	Well	Kitchen Sink	09/21/2008			
	Well	Basement @ Pressure tank	02/08/2010		.22	122.8
			08/26/2011		122	
	Well	after RO	11/17/2011		200	264
	Well	Other (list)	11/21/2011		260	150.7
	Well	system shed	11/08/2011		560	157.5
	Well	after treatment system	10/25/2011		740	261.5
	Well	system shed	11/17/2011		830	222.8
	Well	Other (list)	12/01/2011		940	199.7
	Well	At Pressure Tank in Basement	11/03/2011		1100	152.5
	Well	System Shed	08/31/2011		13000	-82.6
	Well	Pressure Tank	06/20/2009		18000	-165.5
	Well	Pressure Tank	07/22/2010		18000	-76.5
	Well	Pressure Tank	05/24/2011		19000	-91.8
	Well	Pressure Tank	05/10/2011		20000	-138.1
	Well	At Pressure Tank in Basement	08/03/2011		20000	-108
	Well	Pressure Tank	07/06/2011		21000	-77.4
	Well	Basement Before Water Treat	02/26/2009		22000	
	Well	Pressure Tank	03/22/2011		22000	20.1
	Well	Pressure Tank	04/26/2011		22000	154.4
	Well	Pressure Tank	05/14/2009		23000	
	Well	Pressure Tank	06/10/2011		23000	-132.8
	Well	Basement pressure tank	06/21/2011		23000	
	Well	Pressure Tank	04/19/2010		24000	-127
	Well	Pressure Tank	11/22/2010		24000	194.8
	Well	Pressure Tank	02/04/2011		24000	-154.4
	Well	Pressure Tank	04/05/2011		24000	-153.6
	Well	Pressure Tank	09/17/2010	.059	25000	-98.5
	Well	Pressure Tank	04/12/2011		25000	-78.5
	Well	Other (list)	01/05/2012		26000	58.4
			08/26/2011		26600	
	Well	Pressure Tank	12/21/2010		27000	-138.3
			10/06/2010	.056	27800	
	Well	Pressure Tank	08/17/2009		28000	
	Well	Basement Pressure Tank	11/19/2009		28000	-177.4
	Well	Pressure Tank	01/20/2011		28000	13.4

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	Pressure Tank	02/22/2011		28000	-126.1
Well	At Pressure Tank in Basement	07/20/2011		28000	29
Well	At Pressure Tank in Basement	08/17/2011		28000	-123.1
Well	Outside Faucet	10/25/2011		28000	90
Well	Other (list)	12/20/2011		28000	72.7
Well	Pressure Tank	03/09/2011		29000	-111.1
Well	Other (list)	11/21/2011		30000	-10.2
Well	Other (list)	12/08/2011		30000	62.5
Well	At Pressure Tank in Basement	11/08/2011		31000	20.9
Well	PRESSURE TANK	01/11/2010		32000	-164.5
Well	Pressure Tank	01/10/2011		32000	-151.9
Well	Kitchen Sink	11/19/2009		34000	-183.9
Well	before treatment system in system	11/17/2011		35000	63.4
		12/01/2009		42500	
		06/16/2010	.061	51900	
		09/02/2008			
Well	Pressure Tank	04/05/2011			-153.6
Well	Pressure Tank	05/10/2011			-138.1
Well	Kitchen Sink Faucet	04/01/2009		.97	163
Well	Faucet	09/21/2009		1400	79.9
well	Spigot Under Trailer	10/22/2009		1500	56.4
Well	Outside Faucet	10/27/2011		1850	
		08/11/2010	.04	1920	
		08/04/2010	.038	2020	
		07/15/2010	.08	2480	
		07/21/2010	.048	2490	
Well	Spigot Under Trailer	05/14/2009		2500	73.9
		10/14/2010	.077	2570	
		09/09/2010	.024	2690	
		08/27/2009	.105	2720	
Well	Kitchen Sink Faucet	11/24/2009		3100	47.4
well	Bathroom Sink	01/11/2010		3100	51.6
well	OUTSIDE FAUCET	02/02/2010		3100	99.3
well	Outside Faucet	05/27/2010		3100	119.4
Well	Outside Faucet	07/29/2011		3180	
		08/24/2010	.054	3320	
well	Outside Faucet	06/17/2010		3500	137
		10/28/2010	.068	3560	
		12/02/2010	.068	3570	
		08/18/2010	.056	3610	
Well	Kitchen Sink Faucet	08/13/2009		3900	50
Well	Kitchen Sink	10/22/2009		3900	37.2
well	Outside Faucet	03/06/2010		3900	142.9
		11/23/2010	.074	3940	
		09/22/2010	.06	3990	
		12/08/2010	.088	4010	
		11/02/2010	.067	4190	
Well	Outside Spigot	04/27/2010		4200	90.7
		06/24/2009	.043	4230	
Well	Kitchen Sink Faucet	07/20/2009		4300	57.7
Well	Kitchen Sink Faucet	01/06/2009		4700	
Well	Kitchen Sink Faucet	06/20/2009		4800	20.4
		04/27/2010	.047	5250	
		03/18/2009	.051	7360	
		01/26/2009		8200	
		02/23/2009		11500	
		05/08/2008	.028		
Well	Kitchen Sink	09/14/2008			
Well	Well	09/27/2008			
		12/17/2008	.057		
Well	Well	08/06/2008			
		08/11/2010	.038	0	
Well	At Hydrant on top of Well	10/11/2011		.23	234.2
Well	At Well Head from Spigot	07/15/2010		.49	60.8
Well	After Treatment System	07/29/2010		.51	114
Well	Spigot off of filter	08/19/2010		.51	115.3
Well	After Filter	08/26/2010		.64	14.6
Well	Spigot off of Filter	09/02/2010		.66	111.6
Well	After Filter	08/06/2010		.71	175.6
Well	AT well hydrant after filter	08/12/2010		.78	127.4
Well	At Well Head from Spigot	07/22/2010		.81	73.1
well	AFTER FILTER AT HYDRANT	06/24/2010		1	149.7
Well	Pressure Tank Before Filter	06/03/2010		1.6	120.2
well	PRESSURE TANK AFTER FILTER	06/03/2010		2	110.4
Well	Hydrant after Filter	07/08/2010		2.2	47.7
well	OUTSIDE HYDRANT WITH FILTER	06/10/2010		3.7	104.4

land_owner
Ex. 6 -- Personal Privacy

water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Well	Outside Hydrant	12/21/2010		4.8	111.1
Well	Spigot off of Filter	09/09/2010		6.7	151.7
well	OUTSIDE HYDRANT AFTER	06/17/2010		7.1	136
well	HYDRANT AFTER FILTER	07/01/2010		9.7	105.7
		08/18/2010	.055	11.4	
well	PRESSURE TANK SPIGOT	05/20/2010		13	167.2
		09/02/2010	.056	13.2	
		09/09/2010	.067	18.3	
		08/24/2010	.054	19.6	
well	PRESSURE TANK AFTER FI	06/14/2010		29	121.3
Well	At Hydrant on top of Well	09/15/2011		40	218.9
Well	At Well Head from Spigot	01/05/2012		40	149.7
		12/07/2010	< .01	42.9	
well	PRESSURE TANK NEAR WE	05/27/2010		43	123.6
		09/30/2010	.065	49.9	
Well	Outside Hydrant	03/03/2011		93	129.6
		10/14/2010	.016	218	
Well	At Hydrant on top of Well	08/31/2011		240	71.3
Well	At Hydrant on top of Well	09/28/2011		240	179.6
Well	Outside Hydrant	12/20/2011		300	178
Well	Kitchen Sink Faucet	09/23/2010		320	174.2
Well	At Well Head from Spigot	11/21/2011		410	241.9
Well	Outside Hydrant	01/20/2011		430	142
Well	Outside Hydrant	01/07/2011		480	131.6
Well	Outside Hydrant	04/26/2011		510	72.9
Well	At Hydrant on top of Well	10/25/2011		540	94.6
Well	At Hydrant on top of Well	08/03/2011		560	115
Well	Outside Hydrant	02/03/2011		570	86.9
Well	At Hydrant on top of Well	08/17/2011		570	125.9
		10/28/2010	.016	580	
		05/27/2010	.047	610	
Well	Outside Hydrant	12/08/2011		620	118.8
Well	Outside Hydrant	06/21/2011		680	69.6
Well	Outside Hydrant	02/17/2011		690	182.7
Well	Outside Hydrant	05/10/2011		770	58
Well	Outside Hydrant	03/17/2011		780	121.5
Well	Outside Hydrant	04/19/2011		780	172.1
Well	Outside Hydrant	05/24/2011		940	133.9
Well	at hydrant on top of well	11/08/2011		970	252
		12/02/2010	< .01	1040	
		11/22/2010	< .01	1080	
		05/13/2010	.374	1180	
Well	Outside Hydrant	06/07/2011		1400	87.8
well	OUTSIDE SPIGOT	05/15/2010		1500	103.8
Well	Basement at Pressure Tank	10/01/2010		1600	58.7
Well	Outside Hydrant	07/06/2011		1700	241.8
		11/02/2010	.012	1750	
Well	HYDRANT FROM WELL	05/13/2010		2000	-25.1
		11/09/2010	< .01	2130	
well	PRESSUE TANK - AFTER FI	10/30/2009		2300	-163.9
Well	Kitchen Sink Faucet	10/30/2009		3000	-111.5
Well	Outside Hydrant	07/20/2011		3500	147
		02/23/2009		3610	
		05/13/2008			
Well	Kitchen Sink	11/05/2008			
Well	Pressure Tank	05/16/2010			
Well	Pressure Tank	05/18/2010			
		08/31/2010	< .01		
Well	Kitchen Sink	12/04/2010		.26	203.7
well	BASEMENT AT PRESSURE	12/16/2009		15	169.6
		08/07/2009		36	
		09/21/2008			
Well	1ST FLOOR BATHROOM SIN	12/03/2009			53.1
Well	Pressure tank	12/05/2011		< 5	
Well	Kitchen Sink	11/09/2009		.47	192
Well	In Shed at Pressure Tank	11/09/2009		.69	194.5
		10/21/2009	.01	10.8	
		03/17/2010	< .01	14.9	
		03/26/2009	< .01	17.6	
		01/05/2009		< 7.92	
		01/08/2009		< 7.92	
		05/29/2009	< .01	0	
Well	Basement before filter	03/12/2009		< .1	116.6
		07/31/2008			
		12/13/2009		.12	58.3
		12/13/2009		.31	75.4

land_owner	water_source	sample_location	sample_date	Manganese	Methane_ug_l	Orp_mv
Ex. 6 -- Personal Privcy	Well	Kitchen Sink	11/09/2009		< .1	171.8
	Well	Basement at Pressure Tank	11/09/2009		< .1	172.4